

v0.40.2 Mar 27, 2017

JA37-300

Fixed: Data read of analog trigger values.

Fixed: Thermocouple parking register values not being set correctly.

Fixed: Setting Message 2 Sensor Type to Transducer disabled the Trigger Level slider.

v0.40.1 Jan 26, 2017

JA94-001A, JA94-002A, JA94-044A

Changed: Do not use alternate Tx Levels table for Serial#s below 3019.

v0.40.0 Jan 20, 2017

JA94-001A

New Module: Same as the JA94-001.

JA94-002A

New Module: Same as the JA94-002.

JA94-044A

New Module: Same as the JA94-044.

JA33-001

New: Settings Panel now includes a list of Audio Music Systems to choose from when the BT Profile is set to A2DP Source.

New: Added Audio Music Systems editor panel.