

JA95-R04

New Initial Release. T240

JRAC2-001, JRAC2-004

Fixed USER2 COM6/10 DEFAULT Configuration I/O line not being set correctly. Bus 1 Dev 0xAE IO\_7.  
Andrew H Bug

Fixed COM9/10 Artificial Sidetone Enable line states were being reversed when programming the latching relays. This caused Data Check Errors on the next read of the product. Andrew H Bug