

ProCS Release Notes

Version: 0.49.5 Released: May 23, 2018

This release updates the JA95-043 and the JRAC2-001 and fixes some issues.

JA37-001

Fixed: Rx Audio Level sliders not being disabled properly after reading data from product.

Fixed: Data CRC Errors after writing to the product.

Appeared to be a timing issue when writing to the Device 0 EEPROM.

JA95-043

Changed: Modified to support the new JA95-51 and JA95-52 subassemblies for Serial#s 4500 and above.

JA95-R03, JA95-R04

Fixed: ICS Tie Line: gui controls not being enabled/disabled correctly.

JRAC2-001

Changed: Modified to support the new JA95-51/52/53/54 subassemblies for Serial#s 4500 and above.